

Cleaning of potable water reservoirs in The US by Extech LLC, CT





3.0MG Steel Standpipe in CT 78 ft dia. by 80 ft tall

Smaller reservoir in UTAH

Up until today approximately 225 reservoirs have been cleaned by Extech LLC with the Weda VR-600 system

A few examples from some major cleaning assignments:

- Natgun 5.0MG Above ground concrete Tank Pittsfield, MA 135 ft diameter with 8-inches of sediment took 5 days
- Underground Concrete Tank, Toledo, Ohio, 250ft by 400 ft long with 6-6 inches of sediment took 25 days
- Waimia Reservoir, Waikoloa, HI 300 ft x 150 ft 10-16 inches of sediment took
 14 days with two machines.